



ATS Survey Adapters

a vital part of Traceable 3D®

Traceable 3D quality assures your project over time by establishing repeatable benchmarks that efficiently support data capturing and analysis of 3D point clouds in a traceable and reusable process



12 mm L Pin



5/8" or M8

Attach the prism pole adapter to your prism pole.

Attach the reference of your choice to the precision washer, at the top of prism pole adapter.



Workflow ATS Scan Reference System

- 1 Mount precision washers where the references should be placed, walls, ceilings etc.



- 2 Attach references (large or medium) to the washer, magnetic connection

Scan!

Remove the scan references



- 3 Attach prisms, magnetic connection

Survey!

Remove prisms



- 4 Mount Adapter with washer to benchmark

Connect to geo-reference data



ATS Advanced Technical Solutions AB
Krokslättsgatan 7
SE-431 67 Mölndal
SWEDEN

Phone +46 (0)31 20 96 16
www.ats.se